



122 MADISON
SAN ANTONIO, TX 78204

PHONE: (210) 227-8786

FAX: (210) 227-8030

INFO@OURKWA.ORG

WWW.OURKWA.ORG

November 2, 2016

Historic and Design Review Commission
1901 S Alamo Street
San Antonio, Texas 78204

Re: Case #2016-5651: 435 Cedar – *King William District*
Certificate of Appropriateness – Demolition and reconstruction of garage and carport

Dear HDRC Commissioners,

The King William Association Architectural Advisory Committee reviewed the project and concur with staff recommendation to approve the application. We suggest that the gable end vent be rectangular in shape and not replicate the historically inaccurate application of spaced vertical boards that were added to the historic structure in a previous project.

We applaud the applicant for providing very clear and detailed drawings to support the application.

Best Regards,

Mickey Conrad
Chair, Architectural Advisory Committee

Chris Price
President, KWA Board of Directors